Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH2595Work Order Type: WeatherizationAudit Name: 13013SH2595

CLIENT INFORMATION

Client ID: 13013SH2595

AGENCY INFORMATION

Client ID: 13013SH2595

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: WOOD, JIM Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

	Measure 1 Infilt	ration Redctn			Componen	ts			Inspected
C	BLOCK A REHANO WEATHI REPLAC REPLAC	AND SEAL A/C UNIT CO AND SEAL A/C UNIT CO G FRONT DOOR. ERSTRIP AND THRESI CE ATTIC STAIRS UNIT CE DOOR ONLY (META CE BROKEN PANE (8X1	OMPLETE HOLD FRO (53X24). L) @BACk	IN WA ONT DO	ALL (INSIDE) WALL	3		
					Estimated	·		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	Infiltration Reduction	Each	1					
C	Other Detail								
				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:								
	<i>Measur</i> e 2 Repl	ace Htg. System	FOR BOILE		Componen SAL).	ts HS1			Inspected
	<i>Measur</i> e 2 Repl	•	FOR BOILE		-			Actual	Inspected
C	<i>Measur</i> e 2 Repl	•	FOR BOILE		GAL).		Qty		Inspected Total
<i>C</i>	Measure 2 Replace Comment REPLACE Material / Labor	E EXPANSION TANK F		ER (8 C	GAL). Estimated	·	Qty	Actual	
C # 1	Measure 2 Replace Comment REPLACE Material / Labor	Description / Comment	Units	Qty	GAL). Estimated	·	Qty	Actual	
C # 1	Measure 2 Replacement REPLACEMaterial / Labor Heating Equipmen	Description / Comment Replacement Boiler	<i>Units</i> Each	ER (8 0	GAL). Estimated	·	Qty	Actual	
C # 1	Measure 2 Replections Replace Material / Labor Heating Equipmen Labor	Description / Comment Replacement Boiler	<i>Units</i> Each	ER (8 0	GAL). Estimated	·	Qty	Actual	
C # 1	Measure 2 Replections Replace Material / Labor Heating Equipmen Labor	Description / Comment Replacement Boiler	<i>Units</i> Each	ER (8 0	GAL). Estimated	·		Actual	
C # 1	Measure 2 Replections Replace Material / Labor Heating Equipmen Labor	Description / Comment Replacement Boiler	Units Each Each	Qty 1 1	GAL). Estimated	·		Actual	
C # 1	Measure 2 Replections Replace Material / Labor Heating Equipmen Labor	Description / Comment Replacement Boiler	Units Each Each	Qty 1 1	Estimated Unit Cost	·		Actual Unit Cost	
C # 1	Measure 2 Replacement REPLACEMaterial / Labor Heating Equipmen Labor Description	Description / Comment Replacement Boiler	Units Each Each	Qty 1 1	Estimated Unit Cost	·		Actual Unit Cost	
C # 1	Measure 2 Replacement REPLACEMaterial / Labor Heating Equipmen Labor Description	Description / Comment Replacement Boiler	Units Each Each	Qty 1 1	Estimated Unit Cost	·		Actual Unit Cost	

Client ID: 13013SH2595 Work Order Bid (ID)

DOE Weatherization Assistant Version 8.6.0 Page 2 of 5

Measure 3 Use	er-Spec Ceiling R			Componen	<i>t</i> s A1		1	nspected	
Comment ADD R	-19 1586 SQ FT								
			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Attic Insulation - Blown Cellulose - R-19	SqFt	1586						
2 Labor	Attic Insulation - Blown Cellulose - R-19	SqFt	1586						
Other Detail									
			Measur	e Sub Total:]	Sub Total:		
Field Notes:						J			
Comment R-19 1 GROUI	or Ins. R-19 586 SQ FT. ND COVER NEEDED. LSPACE DOOR NEEDED) (24X17).		Componen	ts F1		,	nspected	
		,							
# Material / Labor		,		Estimated			Actual		
1 Insulation	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total	
Insulation	Description / Comment Floor Insulation - Fiberglass Batts - R-19					Qty		Total	
2 Labor	Floor Insulation -	Units	Qty			Qty		Total	
	Floor Insulation - Fiberglass Batts - R-19	<i>Units</i> SqFt	Qty 1586			Qty		Total	
	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586			Qty		Total	
2 Labor	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586			Qty		Total	
2 Labor	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586			Qty		Total	
2 Labor	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586 1586					Total	
2 Labor Other Detail	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586 1586	Unit Cost			Unit Cost	Total	
2 Labor	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586 1586	Unit Cost			Unit Cost	Total	
2 Labor Other Detail	Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	<i>Units</i> SqFt	Qty 1586 1586	Unit Cost			Unit Cost	Total	

		Monitor is Needed L 2 CO. MONITORS			Componen	ts		,	Inspected
	omment into it les	L Z GG. MONTONO			Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	CO monitor	Each	2					
2	Labor	Labor	Each	2					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Measure 6 Pres	sureRelief Piping Need	led		Componen	ts			Inspected
		OP T&P VALVE .	ded		Estimated			Actual	Inspected
C	Comment ADD DR	OP T&P VALVE . Description / Comment	Units	Qty	-		Qty		Inspected Total
C	Comment ADD DR	OP T&P VALVE . Description / Comment		Qty 1	Estimated	1	Qty	Actual	
# 1	Comment ADD DR	OP T&P VALVE . Description / Comment	Units	_	Estimated	1	Qty	Actual	
# 1	Comment ADD DR Material / Labor Health and Safety	Pressure relief piping	<i>Units</i> Each	1	Estimated	1	Qty	Actual	
6 # 1 2	Comment ADD DR Material / Labor Health and Safety Labor	Pressure relief piping	<i>Units</i> Each	1	Estimated	1	Qty	Actual	
6 # 1 2	Comment ADD DR Material / Labor Health and Safety Labor	Pressure relief piping	<i>Units</i> Each	1	Estimated	1	Qty	Actual	
6 # 1 2	Comment ADD DR Material / Labor Health and Safety Labor	Pressure relief piping	Units Each Each	1 1	Estimated	1		Actual	

1	Measure 7	-	or Barrier Needed ement/CrawIspace)			Componer	its		1	Inspected
C	Comment									
						Estimated	1		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and S	Safety	Basement / crawlspace vapor barrier	SqFt	1586					
2	Labor		Labor	SqFt	1586					
(Other Detail				1			-		
L										
					Measur	e Sub Total:			Sub Total:	
	Field Notes:									
				Work O	rder Gra	nd Total:		Gran	d Total:	

Client ID: 13013SH2595